

Software Training Courses	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	No. of Days
<b>Coordinate Measuring Machine</b>													
MCOSMOS Geopak - MAN	9 - 11	6 - 8	6 - 8	10 - 12	2 - 4	5 - 7	3 - 5	1 - 3	4 - 6	2 - 4	6 - 8	4 - 6	3
MCOSMOS Geopak - CNC	9 - 12	6 - 9	6 - 9	10 - 13	2 - 5	5 - 8	3 - 6	1 - 4	4 - 7	2 - 5	6 - 9	4 - 7	4

<b>Vision Measuring Machine</b>													
QVPak	16 - 18	13 - 15	13 - 15	3 - 5	15 - 17	12 - 14	10 - 12	14 - 16	11 - 13	9 - 11	13 - 15	11 - 13	3
QSPak	19 - 20	16 - 17	16 - 17	6 - 7	18 - 19	15 - 16	13 - 14	10 - 11	14 - 15	12 - 13	16 - 17	14 - 15	2

<b>Form Measuring Machine</b>													
Formtracepak-SV	25	22	29	26	24	28	26	23	27	25	22	20	1
Formtracepak-CV	23 - 24	20 - 21	27 - 28	24 - 25	22 - 23	26 - 27	24 - 25	21 - 22	25 - 26	23 - 24	20 - 21	18 - 19	2
Formtracepak-SVC	23 - 25	20 - 22	27 - 29	24 - 26	22 - 24	26 - 28	24 - 26	21 - 23	25 - 27	23 - 25	20 - 22	18 - 20	3
Roundpak	26 - 27	23 - 24	30 - 31	27 - 28	25 - 26	29 - 30	27 - 28	24 - 25	28 - 29	26 - 27	23 - 24	28 - 29	2

Small Tools	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	No. of Days
Calibration of Small Tools	26 - 27	23 - 24	30 - 31	27 - 28	25 - 26	29 - 30	27 - 28	24 - 25	28 - 29	26 - 27	23 - 24	28 - 29	2

Metrology Training Courses	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	No. of Days
Fundamentals of Precision Measurement	17	14	14	4	16	13	11	15	12	10	14	12	1
Dimensional Measurement Metrology	24 - 25	21 - 22	28 - 29	25 - 26	23 - 24	27 - 28	25 - 26	22 - 23	26 - 27	24 - 25	21 - 22	26 - 27	2
Basic Geometric Dimensioning and Tolerancing	19	16	16	6	11	15	13	10	14	12	16	14	1
Basic Introductions to Optics, Surface Parameters, Statistics Control Concepts and Hardness Testing	5	10	2	5	9	1	17	8	18	16	20	18	1

1. Minimum class size is needed for all courses to run.
2. All training to be held in Mitutoyo Singapore.
3. Schedule is subjected to change.

**CONTACT US FOR MORE ENQUIRIES**